

PODUSZKA ZAWIESZENIA Goodyear 566-22-3-517 , HS507149 , 1R11-825 – KOMPLETNA 4R-395/BIC-DF/RP

ZASTOSOWANIE – DAF LF 45

ZAMIENNIK – Goodyear 566-22-3-517, Hendrickson HS 507149,
1R11-825 , 1R11-737 , Daf 1405407 , DT 5.10266

PRODUCENT – Rolgum, Poznań, PL

